



Application for Disaster Recovery Assistance
Under the DRAO Guidelines for Not-For-
Profit-Organization

Supporting Pictures for the Mississippi
Golf Club Application

August 07, 2019

Picture 1 - 18th hole fairway - April 22/19



Picture 2 – Tributary crossing fairways on the 10th and 18th holes - April 22/19



Picture 3 - 18th hole fairway and right hand cart path
with washed out irrigation pipe - April 22/19



Picture 4 - 18th hole right-hand cart path
with washed out irrigation pipe - April 20/19



Picture 5 - 18th hole right-hand cart path – May 4/19



Picture 6 - 18th hole right hand cart path
with washed out irrigation pipe – May 4/19



Picture 7 - 18th hole right-hand cart path
with washed out irrigation pipe – May 4/19



Picture 8 - Dredging of tributary bed on the 18th hole
Material from washed out right-hand cart path over culvert - July 25/19



Picture 9 - Repaired right-hand cart path over culvert on the 18th hole – July 26/19



Picture 10 - Repaired damaged fairway and reburied irrigation line on the 18th Hole fairway – July 26/19



Picture 11 - Location of the washed out left-hand cart bridge on the 18th Hole - May 4/19



Picture 12 - Repositioned left-hand cart bridge on the 18th hole – July 26/19



Picture 13 - Repositioned left-hand cart bridge on the 18th hole – July 26/19



Picture 14 – Tributary crossing fairways on the 10th and 18th holes with the washed out left-hand cart bridge from the 18th hole - April 22/19



Picture 15 – Tributary crossing fairways on the 10th and 18th holes - April 30/19



Picture 16 – Tributary crossing fairways on the 10th and 18th holes – July 26/19



Picture 17 - 1st hole right-hand cart path over culverts - April 22/19



Picture 18 - 1st hole right-hand cart path over culverts - April 25/19



Picture 19 - Washed out 1st hole right-hand cart path over culverts - May 04/19



Picture 20 - Washed out 1st hole right-hand cart path - May 04/19



Picture 21 - Repaired right-hand cart path on the 1st hole over culverts with additional culverts installed – July 26/19



Picture 22 - Repaired right-hand cart path on the 1st hole over culverts with additional culverts installed – July 26/19



Picture 23 - Repaired right-hand cart path and fairway on the 1st hole - July 26/19



Picture 24 – Dredged tributary bed on the 1th hole
Material from washed out right-hand cart path over culvert - July 26/19



Picture 25 - Tributary crossing the 1st hole fairway - April 30/19



Picture 26 - Tributary crossing the 1st hole fairway – July 26/19



Picture 27 - 16th hole green and fairway - April 30/19



Picture 28 - Debris on the 16th hole - May 04/19



Picture 29 - 16th hole green and fairway – July 26/19



Picture 30 - Washed out east cart path approach to the covered bridge on the 5th hole - April 25/19



Picture 31 - Washed out east cart path approach
to the covered bridge on the 5th hole - April 30/19



Picture 32 - Washed out west cart path approach to the covered bridge on the 5th hole - April 30/19



Picture 33 - Washed out concrete support slabs from the covered bridge - July 24/19



Picture 34 - Washed out concrete support slabs from the covered bridge - July 24/19



Picture 35 - Repaired west cart path approach
to the covered bridge on the 5th hole – July 11/19



Picture 36 - West cart path approach to the covered bridge on the 5th hole with new support structure and additional culverts – July 11/19



Picture 37 - East cart path approach to the covered bridge on the 5th hole with new support structure and additional culverts – July 11/19



Picture 38 - Repaired east cart path approach
to the covered bridge on the 5th hole – July 11/19

